



Part No	Inductance (μH)	Tolerance	Temperature Rise Current Typ. (A)	Satura on current Typ. (A)	DCR Typ. (m Ω)	DCR Max. (m Ω)
MD5020-150M	15.0	±20%	1.9	2.8	240	270
MD5020-220M	22.0	±20%	1.5	1.8	350	390

Opera ng temperature: -40°C ~ +125°C

Temperature rise current : The actual value of DC current when the temperature rise is T+40°C

Satura on Current that will cause ini al inductance to drop 20% approximately .



